

TOP SECRET**PRIORITY**

OUT57353

TOP SECRET 110051Z

PRIORITY ☐ CITE ☐ 6088

1965 DEC 11 01 13Z

25X1

IDEALIST

ATTENTION: ☐

25X1

SUBJECT: EVALUATION OF MISSION C595C

13 DEC 1965

1. CAMERA 119 WAS USED IN MISSION C595C FLOWN ON 23 NOVEMBER 1965. PROCESSING WAS ACCOMPLISHED IN THE FIELD.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND RESOLUTION IS GOOD.

B. 9R SIDE: IRREGULAR PLUS DENSITY STREAKS ARE PRESENT

INTERMITTENTLY ON BOTH EDGES THROUGHOUT THE MISSION. EXAMPLES OF

THE STREAKS ARE ON FRAMES 40, 483, 903, 1553, AND 1823. SEVERAL

FINE PLUS DENSITY STREAKS ARE PRESENT PERIODICALLY WITHIN 0.5

INCHES OF BOTH EDGES THROUGHOUT. INTERMITTENT PLUS DENSITY STREAKS

ARE LOCATED 1.5 AND 1.7 INCHES FROM THE INBOARD EDGE ON FRAMES

THROUGH 1330. A FLARED PATTERN OF FOG EXTENDS APPROXIMATELY 3

INCHES INTO THE OUTBOARD EDGE OF FRAMES 1315, 1320, AND 1332.

A MANUFACTURER'S SPLICE IS INSIDE THE FORMAT OF FRAME 1006. HEAT

SPLICES ARE BETWEEN FRAMES 293/294, 558/559, 973/974, 1343/1344,

AND 1778/1779.

DISTRIBUTION		
Cy No.	Office	Action
1	File	
2	OS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3,4	TID	✓
	IAD	
	PAG	
	DIAXX-4	
666	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy
Sanitized

C. 9L SIDE: ROLLER CHATTER WAS NOTED ALONG THE INBOARD EDGE THROUGHOUT. A ROW OF MINUS DENSITY DOTS 2" FROM THE OUTBOARD EDGE AND 1.5" APART STARTING ON FRAME 158 ARE ONLY DETECTABLE FOR APPROXIMATELY ONE HUNDRED FRAMES. HEAT SPLICES ARE PRESENT BETWEEN FRAMES 287/288, 567/568, 1337/1338, 1727/1728, AND IN THE FORMAT OF FRAME 1008. A MANUFACTURING SPLICE IS LOCATED IN FRAME 1004.

TOP SECRET

-2-

D. EDGE STATIC WAS NOTED ON BOTH EDGES OF BOTH CAMERAS THROUGHOUT THE MISSION. THE FIRST TITLED FRAME IS 5 AND THE LAST TITLED FRAME IS 1844.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURED OR DEGRADED APPROXIMATELY 20 PERCENT OF THE MISSION.

T O P S E C R E T

--END OF MESSAGE--

1